

JRT200 INFRARED THERMOMETER



Dual mode | Infrared sensor | Fast - convenient

Specifications:

Temperature range:

32-42.9°C

Maximum allowable error:

In the range of 35.0-42.0°C,
Allowable error $\pm 0.2^{\circ}\text{C}$

In the range of less than 35.0°C and more than 42.0°C,
Maximum allowable error $\pm 0.3^{\circ}\text{C}$

Resolution:

0.1°C

Measure position:

Within 2.5cm of measure object

Power management:

Automatically shutdown during waiting

Battery:

DC3V (2 AAA batteries)

Working and storage conditions:

Temperature range:

Normal working: 16-35°C

Transportation and storage: -20-55°C

Humidity range:

Normal working: $\leq 85\%$ (Non-condensing)

Transportation and storage:
 $\leq 95\%$ (Non-condensing)

Atmospheric pressure:

Normal working: 700-1060hPa

Transportation and storage: 500-1060hPa